

IMPORTANT CANDLE SAFETY TIPS

- 1. Trim candle wick to 1/8" before lighting**, and keep wick trimmed to 1/8" while burning. "Clip Your Wick" Wick Trimmers are available through Specialty Pet Products.
- 2. Always burn candle on a heat resistant surface**, preferably on a heat and fire resistant candle holder.
- 3. Burn candle within sight**, never on or near anything that can catch fire. For best results, burn candle 3-4 hours and extinguish.
- 4. Do not let matches, wick trimmings or debris accumulate in the jar**, as this could be a fire hazard.
- 5. If flame smokes**, extinguish and trim wick to 1/8" before relighting.
- 6. NEVER leave a burning candle unattended.**



Love our candles? Try our other Odor Exterminating products today:
Air Freshener Sprays | Car Fresheners | Fabric Refreshers

SPECIALTY PET PRODUCTS, LLC
1-866-540-7457

6401 Carmel Road, Suite 206 | Charlotte, NC 28226
www.petcandles.com | www.clipyourwick.com

GENERAL CANDLE RULES

- Burn candle within sight, never on or near anything that can catch fire. NEVER leave a burning candle unattended.
- Keep burning candles out of reach of children & pets. Do not burn around birds.
- Do not let matches, wick trimmings or debris accumulate in the jar, as this could be a fire hazard.
- Always burn candles on a heat resistant surface, preferably on a heat and fire resistant candle holder.
- Burn candle in an area away from flammable materials, free from drafts and not near any other heat sources.
- Keep candle wick trimmed to 1/8" at all times. "Clip Your Wick" Wick Trimmers are available through Specialty Pet Products.
- Make sure the candle wick is centered and the flame never touches the glass.
- To reduce possibility of smoking or sooting, keep wick trimmed to 1/8" at all times.
- If smoking occurs, extinguish candle, re-trim wick to 1/8", remove any trimmings or debris and relight candle.
- To extinguish flame, place the metal lid over the jar, as this will minimize smoking.
- Should the jar become blackened, extinguish flame, allow candle to cool, and wipe inside of jar with a paper towel to clean off residue.
- Burn candle until 3/4" of wax remains and discard, as glass may shatter. Do not refill jar with wax.
- Glass jars are fragile, so handle with care. Do not use jars that are cracked, chipped or scratched.
- Wax may be left on the sides of the jar after burning. To minimize this, burn your candle 3-4 hours at a time, until surface is completely liquid. Some wax may still remain, and this is normal, and the amount varies with candle color, fragrance and the burning environment.

SPECIALTY PET PRODUCTS, LLC

1-866-540-7457

6401 Carmel Road, Suite 206 | Charlotte, NC 28226

www.petcandles.com | www.clipyourwick.com